GANN BL H40

1. To begin using device select the Power button below the centre of the screen. The screen will indicate the following items: last measure value in % at the top of the screen, HOLD symbol in the centre, temperature in degrees Celsius and the wood symbol and classification number at the bottom of the screen.

2. A measurement can be taken by pressing the M button in the centre of the meter.

3. To change the timber setting select the down arrow to bring up the timber number and hit the M button. The UP and DOWN arrows can now be used to find the correct number for corresponding timber (full list to be found in manual). Once number has been found pressed the M button to select.

4. To change the surface temperature setting hit the DOWN arrow twice or until the temperature value is isolated. Hit the M button to select the temperature and use the arrow buttons to adjust value. Hold the arrows to increase in increments of 5. Hit the M button to select value.

5. By using the DOWN arrow to scroll through the menu, Maximum, Minimum and saved measurements can be found. Meter will save the last five measurements which can be identified by r1. Click the M button to enter saved values and use the arrows to scroll through saved measurements.

6. To take measurement with probes, select the correct electrode relevant to measurement reading and connect with cables, insert into timber. Once connected with surface temperature entered, and timber category selected hold the M button down to take measurement.

7. If no button is pressed within approx. 40 seconds, the device switches off automatically. The current values are retained and are displayed again after the unit is switched back on.